


FIELD INSPECTION REPORT

Date of Inspection :	17-12-2020	District:	Nalanda
Division :	RWD Hornbait	Length (km):	1.050 Km
Name of the Road:	Taitipura Chandi PWD Road to Kharjamma		
Scheme/Programme:	MAINTENANCE		
Package No.:	Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	S
b)	Condition of Surfacing	S/U	S U
c)	Riding Quality	S/U	U
d)	Road Camber	S/U	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	yes
g)	Compaction of flank/slope & raincuts if any	Yes/No	yes
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	N/A
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	NO
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U


 (Signature)
 17/12/2020

NAME: Raghu K. Maharana
 DESIGNATION: J.E

Scanned with CamScanner

Scanned with CamScanner