FIELD INSPECTION REPORT

Date o	of Inspection: 27	-12.20 District: wat how	
Name of Road:		Porla M.S. to Porla	
Scheme/ Programme:		MAINTENANCE MMUSY (SO)	
Packag		Road ID No.	
Status of the Project:		Onging/Completed/Under Maintenance	
Work is a case of:		New Connectivity/ Up Gradation/ Maintenance	
SLNo		Parameters to be Checked	Remarks
1	Pavement		
a)	Road Junction Condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of Yes		
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slpoe & raincuts if any		Yes/No
2	Cross Drainage		
a)	Condition of headwalls inn Humepipe culverts including its painting S/SRI/U		
b)	Condition of Abutn	S/SRI/U	
c)	Condition of railings/slabs//approach for Bridges		S/SRI/U ↔
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.		
4	Compliance History		
a)	Status of ATR & any others		
The state of the s		Satisfactory (S) Satisfactory but requires Improvement(SRI)	-5-
		Unsatisfactory (U)	

Name: Ramcharda Ram.
Degisnation Junior Enfoncor

(Signature)