FIELD INSPECTION REPORT

Date of	Inspection: 27-12	- 2020 District: 4 (d3V2	and i pur
Name of Road:		pmnsy Road Hurra Hazra to chando pun MAINTENANCE MMNSY (ST)	
Scheme	/ Programme:	MAINTENANCE MM V137 C	
Package		Road ID No.	
	of the Project:	Onging/Completed/Under Maintenance	
		New Connectivity/ Up Gradation/ Maintenance	No.
THE REAL PROPERTY.	s a case of:	Parameters to be Checked	Remarks
Sl.No	of some succession of the succ		S/U
	Pavement Road Junction Condition		S/U S/U
a)	Condition of Surfacing		S/U
b)	Riding Quality		S/U
(c)	D 1 Combon		S/U
	Whether free from defects such as visible cracks, exposed aggregates in case of		Yes/No
e)	CC Pavement		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slpoe & raincuts if any		
2	Cross Drainage S/SRI/U		
a)	Condition of headwalls inn Humepipe curvers including its painting		
b)	Condition of Abutment & Wings walls, Slab in RCC culverts		Sisterio
c)	Condition of railings/slabs//approach for Bridges S/SRI/U 1		
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement Yes/No road markings are provided and maintained.		Yes/No
4	Compliance History		
a)	Status of ATR & any others		NA
Overal	l Grading:	Satisfactory (S) Satisfactory but requires Improvement(SRI) Unsatisfactory (U)	5

Name: Romchande Rom Degisnation Junior Engire

(Signature)