

FIELD INSPECTION REPORT

Date of Inspection: 19.12.20		District: Katihar	
Name of Road: Priyadarshi Tola SE MH. 954 PWD Road MH131A		Road ID No. —	
Scheme/ Programme: MAINTENANCE		Status of the Project: Ongoing/Completed/Under Maintenance	
Package No. —		Work is a case of: New Connectivity/ Up Gradation/ Maintenance	
Sl.No	Parameters to be Checked	Remarks	
1	Pavement		
a)	Road Junction Condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓Yes/No	
2	Cross Drainage		
a)	Condition of headwalls in Humepipe culverts including its painting	— S/SRI/U	
b)	Condition of Abutment & Wings walls, Slab in RCC culverts	— S/SRI/U	
c)	Condition of railings/slabs/approach for Bridges	— S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.	✓Yes/No	
4	Compliance History		
a)	Status of ATR & any others	NO.	

Overall Grading:

Satisfactory (S)	S
Satisfactory but requires Improvement(SRI)	
Unsatisfactory (U)	

Name: Shiv Harayan Mandal
 Designation: AE RW (W) sub OR Amdabad

Signature
 19.12.20
 (Signature)