

FIELD INSPECTION REPORT

MMGSY (SC)

Date of Inspection : 24-12-2020		District: Somastipur
Division : Somastipur		Length (km): 1.46 km
Name of the Road: L 039 to Ramchandra Ram Tola		
Scheme/Programme: MAINTENANCE		MMGSY (SC)
Package No.:		Road Id No.: 3201010396
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U U
c)	Riding Quality	S/U U
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No Yes NO.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U T
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ↓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating : Remark:- Board maintenance rep, RT surface damage, Rain cut in shoulder

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	— U —

NAME: SANTOSH KR. THAKUR
JE, R.W.D.

(Signature)
25/12/20
AE