FIELD INSPECTION REPORT

Date of		23/14020	District: E. Chambaran	
Division: Accres Length (km): 3,846				
		meiziya chou	uk to Barharwa Kalu	ver to lette
	Programme:	MAINTENANCE	2 1112	
Package		- 1 - /C1-4-1	Road Id No.: 3/70230	0304
Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance		
	a case of:			The participation of the
SI. No.		Parameters to	be checked	Remarks
1.	Pavement			and the state of t
a)	Road Junction condition			S/U
b)	Condition of Surfacing			V S/U
c)	Riding Quality			∨ S/U
d)	Road Camber		•	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
f)	Contraction Joints provided or not (CC Pavement)			Xw Yes/No
g)	Compaction of	flank/slope & raincu	nts if any	No Yes/No
2.	Cross Draina	ge - 11.731		AND THE STATE OF STAT
a)	Condition of h	ead walls in Hume pi	pe culverts including its painting	S/SRI/U
b) ·				S/SRI/U
c)	Condition of ra	ailings/slab/approach	for Bridges	// S/SRI/U
3	Road Furnitu			
a)	Whether sign stones/Paveme	boards/informatory. nt road markings are	/cautionary Board/km & 200r provided and maintained	n Yes/No
4.	Compliance i	istory		
a)	Status of ATR'	s & any others		NO

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U
Ousatisfactory (C)	

(Signature)

NAME:

Mhandra Kumen

DESIGNATION: A.E./RWD

Scanned with CamScanner