FIELD INSPECTION REPORT

		6/12/020	District: E-chaopenon		
Division: Aceray			Length (km): 1.667		
			thixor to shuplingonTo	19	
	Programme:	MAINTENANCE	5 P Ba		
Package No.:			Road Id No.: 3/70836133/		
		,	going/Completed/Under Maintenance w Connectivity/Up gradation/ Maintenance		
COOK VIEW COOK	a case of:			The second in the second	
S1. No.		Parameters to		Remarks	
1.	Pavement		Terror suspensive and the suspen	in Combination	
a)	Road Junction	condition		S S/U	
b)	Condition of S	urfacing	W. Silevin	U S/U	
c)	Riding Quality		·	U S/U	
d)	Road Camber			5 \$7U	
e)	Whether free from defects such as visible cracks, exposed Yes/No aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			4 S/SRI/U	
1	Rosil Furniture				
a)	Whether sign	hoards/informatory	/cautionary Board/km & 200m provided and maintained	Yes/No	
74H 85	Compliance I	listory!		The second second	
a)	Status of ATR	's & any others		No	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

74/12/02.0 (Signature)

NAME:

Asholcful

DESIGNATION:

12/AWI

Scanned with CamScanner