

FIELD INSPECTION REPORT

Date of Inspection : 22.12.2020		District: Muzaffarpur
Division : Muzaffarpur East-I		Length (km): 2.245 KM
Name of the Road: NH-77 Fakul/Boring to Kesharwadih Vaichali Siman Tok.		
Scheme/Programme:	MAINTENANCE	MNCS (SC)
Package No.:		Road Id No.: 31507201318
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N.A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

Bijendra Kumar

DESIGNATION:

JE/RWD(LW)
Kyrhami

K Anilash
22/12/20
(Signature)
AE
RWD (LW)
Kyrhami