

FIELD INSPECTION REPORT

Date of Inspection :- 23.11.20	District :- Peta Gaoth	
Division :- Ashgaria	Length (km) :- 2.125	
Name of Road :- P. Devaki P.M.G.S.Y Road to Pabankh Moula in Jaha		
Scheme/Programme :- P.M.G.S.Y	Maintenance	
Package No. :-	Road ID No. :-	
Status of Project :- 5th year maintenance	Ongoing/Complete/Under Maintenance	
Work is a case of :-	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	✓S/U
b)	Condition of Surface	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Construction joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓✓✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

23.11.20
J E / Pabankh
(Signature)