

Inspection of Road Under MMGSY (SC) Road List in Chausa Block

FIELD INSPECTION REPORT

Date of Inspection : 23.12.2020		District: Burari
Division : Buxar		Length (km): 0.700 km
Name of the Road: Chhuni main Road to Gausona		
Scheme/Programme: MAINTENANCE MMGSY (SC) / 2017-18		
Package No.: / 2017-18		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	✓ S/U
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	✓ S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts N.A.	S/SRI/U
c)	Condition of railings/slab/approach for Bridges N.A.	S/SRI/U
3.	Road Furniture	✓ Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires improvement (SRI)	'SRI'
Unsatisfactory (U)	

(Signature) M. Prasad 23.12.2020

NAME: M. Prasad

DESIGNATION: J.E.