

FIELD INSPECTION REPORT

Date of Inspection: 20.12.2020 District: East Chomphon
 Division: Arera Length (km): 0.618
 Name of the Road: Chapisa Hays / Old Road Nanyang Tala to Kanchachwa handola
 Scheme/Programme: MAINTENANCE
 Package No.:

Status of the Project: Ongoing/Completed/Under Maintenance Road Id No.: 31708301332
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S/U
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	Yes/No
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	5
Unsatisfactory (U)	

NAME: H. Narasimha Reddy
 DESIGNATION: Sr. Asst. Engineer
 G. Narasimha

(Signature)

Scanned with CamScanner