

FIELD INSPECTION REPORT

Date of Inspection :- 23.12.20		District :- Khajuraho
Division :- Khajuraho		Length (km) :- 3.345
Name of Road :- Logo - Panna to Bhikharihat Haghurua Road		
Scheme/Programme :- Priority		Maintenance
Package No. :-		Road ID No. :-
Status of Project :- 5th Year Maintenance		Ongoing/Complete/Under Maintenance
Work is a case of :-		New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	
b)	Condition of Surface	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ S/U
f)	Construction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	Yes/No ✓
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	NA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 23.12.20
 SP/Planch
 (Signature)