

FIELD INSPECTION REPORT

Date of Inspection: 12.12.2020 District: Patna
 Location: Paliganj Length (km): 0.700
 Name of the Road: Kuskuri tola Midki Nahar to Laxhan tola Govt middle School English medium to Motabali block.
 Scheme Programme: MAHATMA
 Package No.: Road Id No.:

Category of the Project: Orphanage / School Under Maintenance
 Works as a case of: New Connectivity / Up gradation / Maintenance

No.	Parameters to be checked	Remarks
	Pavement	
	Base / Subgrade condition	✓ S
	Condition of Surfacing	✓ S
	Rides Quality	✓ S
	Road Camber	✓ S
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
	Contraction Joints provided / not (CC Pavement)	Yes/No
	Condition of flank slope / shoulders if any	Yes/No
	Cross Drainage	
	Condition of head walls in Dime pipe culverts including its painting	S/SRI/U
	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
	Condition of railings/slab approach for Bridges	S/SRI/U
	Road Furniture	
	Whether sign boards / regulatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
	Compliance History	
	Details of WTR's & any other	

Rating	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	" SRI "
	Unsatisfactory (U)	

12.12.2020

(Signature)