

FIELD INSPECTION REPORT

Date of Inspection :	20-12-2020	District:	Kishanganj
Division :	Kishanganj-2	Length (km):	0.800 km
Name of the Road:	Fulbharadi Adibadi to Kharkei - (UNWY)		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	21205901896
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U — S
b)	Condition of Surfacing	S/U — S
c)	Riding Quality	S/U — S
d)	Road Camber	S/U — S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U — U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U — S
c)	Condition of railings/slab/approach for Bridges	S/SR/U — SP1
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Construction Material	
a)	Status of ATR's & any others	—

Overall Rating

Satisfactory (S)	—
Satisfactory but requires improvement (SRU)	SP1
Unsatisfactory (U)	—

NAME:

[Signature]
20/12/2020
(Signature)