

FIELD INSPECTION REPORT

Date of Inspection : 22.12.2020	District: Muzaffarpur
Division : Muzaffarpur East-I	Length (km): 1.062 Km
Name of the Road: Railway Gumbi 19 to Gausi Bhagat Singh Yadav Tola	
Scheme/Programme:	MAINTENANCE (MMGSY SE)
Package No.:	Road Id No.: 31507201370
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Some 200m post missing ✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: Bijendra Kumar
 DESIGNATION: JE/RWDLW
Kurhan

K Anilish
22/12/20
 (Signature)
 AE
 RWDLW
 Kurhan