FIELD INSPECTION REPORT

Divisio	it Inspection :	19/12/20 Dis	trict: vaishali		
	10.0		ngth (km): -20		
	c/Programme:	MAINTENANCE	llo school Palesollet x	alt se pade	
	ge No.:	The state of the s	nd Id No.;		
	of the Project: *	Ongoing/Completed/Und	er Maintenance		
Work	is a case of:	New Connectivity/Up gra	dation/ Maintenance		
SL No		Parameters to be cl		Remarks	
1.	Pavement			Remarks	
al	Road Junction condition				
b)	Condition of Surfacing			√S/U	
2000				V S/U	
c)	Riding Quality			VS/U	
4)	Road Camber			V S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
1)	Contraction Joints provided or not (CC Pavement)			Ves/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2,	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U				
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3,	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance His		CARRY NO. 10 September 1	70.50	
a)	Status of ATR's			THE THE WORLD	

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	1000

(Signature)

inta-

NAME:

DESIGNATION: