

FIELD INSPECTION REPORT

Date of Inspection : 24/12/2020	District: P45 m-y
Division : R.W.D. Div - Purnea	Length (km): 3.0/95 K.4
Name of the Road: Badgechhi Mahavi ssha on to Rai Tai 19	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	USU
b)	Condition of Surfacing	USU
c)	Riding Quality	USU
d)	Road Camber	USU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	USU/No
f)	Contraction Joints provided or not (CC Pavement)	USU/No
g)	Compaction of flank/slope & raincuts if any	Yes/No SAT
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	USU/No
4. Compliance History		
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SAT
Unsatisfactory (U)	

NAME: MUNI LAL DAS

DESIGNATION: J.E

Muni Lal Das
(Signature)