

# FIELD INSPECTION REPORT

|                        |                                                      |              |              |
|------------------------|------------------------------------------------------|--------------|--------------|
| Date of Inspection :   | 21.12.20                                             | District:    | Muzaffarpur. |
| Division :             | R.W.D. Muz. West                                     | Length (km): | 1.5          |
| Name of the Road:      | Patu Bakhabahad M.B.S. Road Se Bhatwalia Nahal, Tak. |              |              |
| Scheme/Programme:      | MAINTENANCE                                          |              |              |
| Package No.:           |                                                      | Road Id No.: | 31507401853  |
| Status of the Project: | Ongoing/Completed/Under Maintenance                  |              |              |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance           |              |              |

| Sl. No. | Parameters to be checked                                                                                             | Remarks  |
|---------|----------------------------------------------------------------------------------------------------------------------|----------|
| 1.      | Pavement                                                                                                             |          |
| a)      | Road Junction condition                                                                                              | ✓S/U     |
| b)      | Condition of Surfacing                                                                                               | ✓S/U     |
| c)      | Riding Quality                                                                                                       | ✓S/U     |
| d)      | Road Camber                                                                                                          | ✓S/U     |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | ✓Yes/No  |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | ✓Yes/No  |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | ✓Yes/No  |
| 2.      | Cross Drainage                                                                                                       |          |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | ✓S/SRI/U |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | ✓S/SRI/U |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | ✓S/SRI/U |
| 3.      | Road Furniture                                                                                                       |          |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓Yes/No  |
| 4.      | Compliance History                                                                                                   |          |
| a)      | Status of ATR's & any others                                                                                         | N.A.     |

Overall Rating :

|                                             |    |
|---------------------------------------------|----|
| Satisfactory (S)                            | S. |
| Satisfactory but requires Improvement (SRI) |    |
| Unsatisfactory (U)                          |    |

21.12.20  
(Signature)

NAME: Satya Narayan Pareek  
DESIGNATION: J.E. party