FIELD INSPECTION REPORT

Date of	Inspection: 27		Lan	
Name o	of Road:	PM954 Road Deug	aon to Dhoomnagan So	ruth Tola.
Scheme Programme: MAINTENAI		MAINTENANCE	NEE	
Packag	e No.	Road ID No.		
Status o	of the Project: Onging/Completed/Under Maintenance			
Work is	s a case of: New Connectivity/ Up Gradation/ Maintenance			
SI.No	Parameters to be Checked		Remarks	
1	Pavement			
a)	Road Junction Condition			√8/U
b)	Condition of Surfacing		<i>√</i> 8/U	
	Riding Quality		√ 5 /U	
	Road Camber			√87 U
۵	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No	
_	Compaction of flank/slpoe & raincuts if any		Yes/No	
	Cross Drainage			
a)	Condition of headwalls inn Humepipe culverts including its painting		8/SRI/U	
	Condition of Abutment & Wings walls, Slab in RCC culverts		S/SRI/U	
	Condition of railings/slabs//approach for Bridges		8/SRI/U	
	Road Furniture			
- 1	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.			Yes/No
	Compliance History			
a) S	Status of ATR & any others			
				1.
Sat		tisfactory (S)		S
		Satisfactory but requires Improvement(SRI)		
		Unsatisfactory (U)		

Amandra Neath Traken

Name: +

(Signature)