FIELD INSPECTION REPORT

	Inspection:	24/12/20	District: East Chank	200010
Division	10	10 tihani	Longth (1)	(10(0)
	the Road:	takardui chow		n Tola
Scheme/	Programme:	MAINTENANCE	MMUSY NDB (Briks)	7 /074
Package			Road Id No.:	
Status of	the Project:	Ongoing/Complete	d/Under Maintenance	
	a case of:	New Connectivity/	Up gradation/ Maintenance	
Sl. No.		Parameters to		Remarks
1.	Pavement			Remarks
a)	Road Junction condition			
b)	Condition of Surfacing			S/U
c)				√S/U
	Riding Quality			√S/U
d)	Road Camber			√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head wells in II			
	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U ^
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No ~
4.	Compliance H	listory	Onder Creating Transition (Control of the Control o	electric sections
	Status of ATR'		The state of the s	Mary Spirit and Carlo

Overall Rating

Satisfactory (S)	;
Satisfactory but requires Improvement (SRI)	'SRI'
Unsatisfactory (U)	

NAME: Rajendra Pd- Yadav

DESIGNATION: A-E