


## FIELD INSPECTION REPORT

Date of Inspection: 18.12.2020		District: Kishanganj	
Division: Kishanganj-1		Length(km): 0.800	
Name of the Road: To 2 to Karhui Bari Manza.			
Scheme/Programme:		Urdu.	
Package No.:		Road Id No.: 21205807890	
Status of the Project:		Ongoing/Completed /Under Maintenance	
Work is a case of:		New Connectivity/ Up gradation / Maintenance	
Sl. No	Parameters to be checked	Remarks	
1.	<b>Pavement</b>	✓ S/U	
a)	Road Junction Condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No	
f)	Contraction Joints Provided or not ( CC Pavement)	✓ Yes/No	
g)	Compaction of flank / shop & raincuts if any	✓ Yes/No	
2.	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its Painting	✓ S/SRI/U	
b)	Condition of Abutment & Wing walls, slab in RCC culverts	✓ S/SRI/U	
c)	Condition of railings/Slab/approach for Bridges	✓ S/SRI/U	
3.	<b>Road Furniture</b>		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No	
4.	<b>Compliance History</b>		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory(S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

  
 18-12-2020  
 (Signature)

NAME: Pravind Ravidas  
J.E, RWD, Kochadhaman