FIELD INSPECTION REPORT

Date of Inspection: 2	0.12.2020	District: Muza-flar pur
Division: Muzallorph East-1		Length (km): 0.213KM
Name of the Road: Tu	rki Ramchardze Pa	1th to chadhua Noniga Tola.
Scheme/Programme:	MAINTENANO	CE mmary (sc)
Package No.:		Road Id No.: 31507201390
Status of the Project:		leted/Under Matintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	
c)	Riding Quality	∽S/U
d)	Road Camber	~ 8/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-S/SRI/U
c)	Condition of railings/slab/approach for Bridges	-\$/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	THE S
Unsatisfactory (U)	11/15

Bymv 20.12.2020

NAME:

Bijendan Kymov

DESIGNATION: JEJ RNDLW)
Kurhani

(Signature) AC RNDLW Kurhan