## FIELD INSPECTION REPORT

Date of Inspection: 22.12. 2020		District: Muzatlarper
Division: Muzatlompin East-1		Length (km): 1.047
		hakur Ke Gharto Bhagwanpur Harijan Tola.
Package No.:		Road Id No.: 31507201394
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	l. No. Parameters to be checked		
1.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber	√S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)	Ycs/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-8/SRI/U	
c)	Condition of railings/slab/approach for Bridges	-S∕SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		
a)	Status of ATR's & any others	4. A	

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

22.12.2020

NAME:

By'endan Kumar

DESIGNATION: JE | RWDIW)

Kyrham'

(Signature)

AE

RND LW)

Kyrham'