

FIELD INSPECTION REPORT

Date of Inspection: 20.12.20		District: Katikar
Name of Road: Mohan Kupbi Chowk to Lakhtola ST village		
Scheme Programme: 8th Tak		
Package No.		MAINTENANCE
Status of the Project:		Road ID No.
Work is a case of:		Ongoing/Completed/Under Maintenance
		New Connectivity/ Up Gradation/ Maintenance
Sl No	Remarks	Remarks
1	Pavement	
a)	Road Junction Condition	✓SU
b)	Condition of Surfacing	✓SU
c)	Riding Quality	✓SU
d)	Road Camber	✓SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2	Cross Drainage	
a)	Condition of headwalls in Humepipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wings walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slabs/approach for Bridges	✓S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.	✓Yes/No
4	Compliance History	
a)	Status of ATR & any others	NO

Overall Grading:

Satisfactory (S)	S
Satisfactory but requires Improvement(SRI)	
Unsatisfactory (U)	

Name: Shiv Harayan Bhandal
 Designation: AE Road & Water Div. Andolab

(Signature) 20.12.20