FIELD INSPECTION REPORT

| Date o | of Inspection: 27 | 12-20 | District: Wax har | | |
|--|--|---|---|---------|--|
| Name of Road: SONTO | | | PWD sonaili Pathto hugti Tola (Gogra) | | |
| Scheme/ Programme: MAINTENAN | | | NCE MMNSY (SC) | | |
| Package No. | | | Road ID No. | | |
| Status of the Project: Onging/C | | Onging/Con | mpleted/Under Maintenance | | |
| | | 1 | New Connectivity/ Up Gradation/ Maintenance | | |
| SLNe | | AND DESCRIPTION OF THE PERSON | Parameters to be Checked Remarks | | |
| 1 | Pavement | | | | |
| a) | Road Junction Condition | | | S/U | |
| b) | Condition of Surfacing | | | \$/U | |
| c) | Riding Quality | | | S/U | |
| d) | Road Camber | | | S/U | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement | | | Yes/No | |
| f) | Contraction Joints provided or not (CC Pavement) | | | Yes/No | |
| g) | Compaction of flank/slpoe & raincuts if any | | | Yes/No | |
| 2 | Cross Drainage | | | | |
| a) | Condition of headwalls inn Humepipe culverts including its painting S/SRI/U | | | | |
| b) | Condition of Abutment & Wings walls, Slab in RCC culverts | | | S/SRI/U | |
| c) | Condition of railings/slabs//approach for Bridges | | | S/SRI/U | |
| | Load Fill little | | | | |
| - CALC C | Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained. | | | | |
| 4 | 20mpliance History | | | | |
| a) Status of ATR & any others | | | | | |
| erall Gr | The second secon | ntisfactory (S | | -5- | |
| | I is | nsatisfactor | t requires Improvement(SRI) | | |
| Maintain Ann DILETEY DE BT SIFT SHEW (NH | | | | | |
| maintain, com on the stanting of siles of sally some Ramchande Rom (Signature) (Signature) | | | | | |

Na De