FIELD INSPECTION REPORT

Date of Inspection: \\ .12.2020			District: Kishanganj	
Division: Kishanganj-1			Length(km):	
Name of the Road: Lozgato) to Italicali is Manzabari Parici, way				
Scheme/Programme: PMUSY			. to paticalian	
Package No.: Road Id No.: 212 05800220				
	of the Project:	Ongoing/Compl	eted /Under Maintenance ~	
Work is a case of:		New Connectivity/ Up gradation / Maintenance		
S1. No			s to be checked	Remarks
1.	Pavement S/L			S/U
a)	Road Junction Condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality \\ \sqrt{S/U}			
d)	Road Camber			
e)	Whether free f	as visible cracks, exposed aggregates 🔍	Yes/No	
	in case of CC Pavement.			
f)	Contraction Joints Provided or not (CC Pavement) Yes/No			-
g)	Compaction of flank / shop & raincuts if any Yes/No			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its Painting S/SRI/U			
b)	Condition of Abutment & Wing walls, slab in RCC culverts			
c)	Condition of railings/Slab/approach for Bridges S/SRI/U			S/SRI/U
3.	Road Furniture			
a)	Whether sign b	ooards/informato	ory/cautionary Board/km & 200m 💎 🤇	Yes/No
			s are provided and maintained	
4.	Compliance History			
a)	Status of ATR's	& any others		

Overall Rating:

Satisfactory(S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

(Signature)

NAME: Pravind Ravidas
J.E, RWD, Kochadhaman