

# FIELD INSPECTION REPORT

Date of Inspection: 31.12.2020		District: East Champaran
Division: Buxar		Length (km): 1.540
Name of the Road: SHAKAT TOLA to Le 41		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.: 317e8301244
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
<b>1. Pavement</b>		
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
<b>2. Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
<b>3. Road Furniture</b>		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
<b>4. Compliance History</b>		
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Himanshu Sen

DESIGNATION: Asst. R.O.

Scanned with CamScanner