

FIELD INSPECTION REPORT

Date of Inspection: 27/11/20 District: Purnia
 Division: Dhanboka Length (km): 1.20 km
 Name of the Road: Tol to Santal Naya to to Kikik Dar Adewasi
 Scheme/Programme: MAINTENANCE Tole.
 Package No.: Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	/ S/U
b)	Condition of Surfacing	/ S/U
c)	Riding Quality	/ S/U
d)	Road Camber	/ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	/ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	/ Yes/No
g)	Compaction of flank/slope & raincuts if any	/ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	/ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	/ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	/ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	/ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	1
Satisfactory but requires Improvement (SRI)	1
Unsatisfactory (U)	

NAME: Shailendra Kumar
 A E

(Signature) 27/11/20