

FIELD INSPECTION REPORT

Date of Inspection :	22-12-2020	District:	BUYAR
Division :	DUMRAON	Length (km):	1.00 KM
Name of the Road:	BAGEN DUMRAON PATH TO BAGEN ARION HARIJAN TOLA TAK.		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance ☒		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ☒ yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ☒ yes
g)	Compaction of flank/slope & raincuts if any	Yes/No ☒ NO
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained 200m	Yes/No ☒ No maintained
4.	Compliance History	
a)	Status of ATR's & any others	No.

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

Phan
22-12-2020

J.E.

Maintenance Board is Not in Road.

Phan
22-12-20

(Signature)

NAME: