


FIELD INSPECTION REPORT

Date of Inspection : 15/12/2020	District: Naulada
Division : Rajanli	Length (km):
Name of the Road: NH31 - Madani	
Scheme/Programme: MAINTENANCE	Under 5 year (PMGSY)
Package No.: BR-2SR-044	Road Id No.: 10502702224
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & mircuts if any	✓Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	"SRI"
Unsatisfactory (U)	—

(Signature) 

NAME: - Vinay K. V.

DESIGNATION: CE