


FIELD INSPECTION REPORT

Date of Inspection: 20.12.2020		District: Bhagalpur	
Division: Bhagalpur		Length (Km): 0.700m	
Name of the Road: L033 PWD road No-12 to Sanf Nagar			
Scheme / Programme:			
Package No: BR-D6R-234		Road Id No: 20703202159	
Status of the Project: Ongoing / Completed / Under Maintenance ✓			
Work is a case of: New Connectivity / Up gradation / Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S / U	
b)	Condition of Surfacing	✓ S / U	
c)	Riding Quality	✓ S / U	
d)	Road Camber	✓ S / U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ Yes / No	
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes / No	
g)	Compaction of flank slope & raincuts if any	✓ Yes / No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S / SRI / U	NA
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	
c)	Condition of railings/slab approach for Bridges	S / SRI / U	
3.	Road Furniture		
a)	Whether sign boards / informative / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained	Yes No ✓	
4.	Compliance History		
a)	Status of ATR's & any others	No	
Overall Rating			
	Satisfactory (S)	1	
	Satisfactory but requires Improvement (SRI)	SRI	
	Unsatisfactory (U)	1	

Note: Logo board not paint properly

NAME: Rajkishor Rajak
DESIGNATION: A.E


20.12.2020
Signature A.E