

FIELD INSPECTION REPORT

Date of Inspection : 20.12.2020		District : Bhagalpur	
Division : Bhagalpur		Length (Km) : 1.00 Km	
Name of the Road : L39-pw road No-12 to Malangaachan			
Scheme / Programme : I			
Package No. BR-06R-236		Road Id No. : 20703202166	
Status of the Project : Ongoing / Completed / Under Maintenance ☒			
Work is a case of : New Connectivity / Up gradation / Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	☒ S / ☒ U	
b)	Condition of Surfacing	☒ S / ☒ U	
c)	Riding Quality	☒ S / ☒ U	
d)	Road Camber	☒ S / ☒ U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No ☒	
f)	Contraction Joints provided or not (CC Pavement)	☒ Yes / No	
g)	Compaction of flank/slope & raincuts if any	☒ Yes / No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	☒ S / ☒ SRI / ☒ U	
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	] NA
c)	Condition of railings/slab/approach for Bridges	S / SRI / U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	☒ Yes / No	
4.	Compliance History		
a)	Status of ATR's & any others	NO	
Overall Rating			
Satisfactory (S)			
Satisfactory but requires Improvement (SRI)		SRI	
Unsatisfactory (U)			

Note: Logo board not painted properly
 (1) Flank not maintain properly

NAME: Ratishor Rajah
 DESIGNATION: A.E

Signature 
 20.12.2020
 A.E