## FIELD INSPECTION REPORT

Date of I	nspection :   District : Bhagalpur		
Division: Bhagalpur   Length (Km): 1-1464m			
Name of	the Road: PWD mad no-12 Rumchandra	mo to 13	gind toler
Scheme /	Programme :		
Package l	No.; IMMGSY (se)   Road Id No.: 2070	321301	5
Status of	the Project:   Ongoing / Completed / Under Maintenance		
Vork is a	a case of :   New Connectivity / Up gradation / Maintenance	e	
SL. No.	Parameters to be checked	Remarks	
1.	Pavement	1	
a)	Road Junction condition	SIU	
b)	Condition of Surfacing	VSIU	
c)	Riding Quality	√S/U	
d)	Road Camber	√S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	
1)	Contraction Joints provided or not (CC Pavement)	Wes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage	,	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	7
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SR1/U	
3.	Road Furniture		
a) <sub>.</sub>	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	NO	
verall Ra	ting:	1 /10	
	Satisfactory (S)		
	Satisfactory but requires Improvement (SRI)	1	
	Unsatisfactory (U)	SPI	
	logo board n.A paint proper		

NAME: Radicishor Pasah

DESIGNATION: A.E

Signature 2012.020