

FIELD INSPECTION REPORT

Date of Inspection : 12/12/2020		District: SIKHAN
Division : SIKHAN-01		Length (km): 1,800KM
Name of the Road: Rasulpur to Kohrauli		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project: ☒ Ongoing/Completed/Under Maintenance		
Work is a case of: ☒ New Connectivity/ ☒ Up gradation/ ☒ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U S
b)	Condition of Surfacing	✓S/U S
c)	Riding Quality	✓S/U S
d)	Road Camber	✓S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No No Provisions
f)	Contraction Joints provided or not (CC Pavement)	Yes/No No Provisions
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U Yet To be Done (Cold HPC)
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U Yet To be Done
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yet To be done
4.	Compliance History	
a)	Status of ATR's & any others	NO ATR NO ATR.

Overall Rating :

Satisfactory (S)	✓S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

Mang Kumar

DESIGNATION:

For Chief
(Signature) 12/12/2020