

FIELD INSPECTION REPORT


Date Of Inspection		24/12/2020	District		Bhopur
Division		PIRD	Length (km):		2.50
Name of the Road:		Moapkala Durgasthan to Harpur LooK via Bishampharjour & Lachodidih			
Scheme/Programme		MAINTENANCE			
Package No.:			Road Id No.:		
Status of the Project :		Ongoing/Completed/Under Maintenance			
Work is a case of :		New Connectivity/Up gradation/Maintenance			
SI No.	Parameters to be checked				Remarks
1	Pavement				
a)	Road Junction condition				S/U
b)	Condition of Surfacing				S/U
c)	Riding Quality				S/U
d)	Road Camber				S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement				Yes/No
f)	Contraction Joints provided or not (CC Pavement)				Yes/No
g)	Compaction of flank/slope & raincuts if any				Yes/No
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting				S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U
c)	Condition of railings/slab/approach for Bridges				S/SRI/U
3	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				✓ Yes/No
4	Compliance History				
a)	Status of ATR's & any others				

Overall Rating :

Satisfactory (S)	" S "
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name: Ashok Kumar

Designation SE


 24/12/2020
 (Signature)