

# FIELD INSPECTION REPORT

Date of Inspection : 21/12/2020		District: Siwan
Division : R.I.D. Siwan-01		Length (km): 3.230KM
Name of the Road: TARWARA MAIN PATH TO KAITHE		
Scheme/Programme: MAINTENANCE		(5173)
Package No.:		Road Id No.:
Status of the Project: <input checked="" type="checkbox"/> Ongoing/Completed/Under Maintenance		
Work is a case of: <input checked="" type="checkbox"/> New Connectivity/ <input checked="" type="checkbox"/> Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No No Provision
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No Yet To be done
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U No Provision
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U No Provision
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others	No ATR

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

Checked  
21/12/2020  
Do (Signature)

NAME: Manoj Kumar  
DESIGNATION: EE R.I.D Siwan-01