

### FIELD INSPECTION REPORT

Date Of Inspection <u>24/12/2020</u>		District <u>Bhopur</u>
Division <u>Piro</u>		Length (km): <u>1.825</u>
Name of the Road:	<u>Khutahani Bazar to Miki Sawana</u>	
Scheme/Programme	MAINTENANCE	
Package No.:	Road Id No.: <u>NEW 220001713</u>	
Status of the Project :	Ongoing/Completed/Under Maintenance	
Work is a case of :	New Connectivity/Up gradation/Maintenance	
SI No.	Parameters to be checked	Remarks
1	<b>Pavement</b>	
a)	Road Junction condition	<u>S/U</u>
b)	Condition of Surfacing	<u>S/U</u>
c)	Riding Quality	<u>S/U</u>
d)	Road Camber	<u>S/U</u>
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No <u>NA</u>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No <u>NA</u>
g)	Compaction of flank/slope & raincuts if any	Yes/No <u>NA</u>
2	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<u>Yes/No</u>
4	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	<u>" S "</u>
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name: Ashok Kumar

Ashok  
24/12/2020  
(Signature)

Designation JE