

FIELD INSPECTION REPORT

Date of Inspection : 27/12/2020	District: Nawada	
Division : Nawada	Length (km): 2.28 km	
Name of the Road: Kachana Konyakul to Dettoul Tan		
Scheme/Programme: MAINTENANCE New		
Package No.:	Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓SU
b)	Condition of Surfacing	✓SU
c)	Riding Quality	✓SU
d)	Road Camber	✓SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NAYes/No
f)	Contraction Joints provided or not (CC Pavement)	NAYes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No <i>minors</i>
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NAYS/SRI/U
c)	Condition of railings/slab approach for Bridges	NAYS/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

M/S
27/12/2020
(Signature)

NAME: Sri Kant Prasad.
E.E