

FIELD INSPECTION REPORT

Date of Inspection: 28/04/2020		District: Malanda	
Division: Rajauli		Length (km): 1.250	
Name of the Road: NH 31 to Horrida			
Scheme/Programme: MAINTENANCE		Road Id No:	
Package No.:		Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	N/A/Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	N/A/Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓Yes/No/reinforce	
2.	Gross Drainage		
a)	Condition of head walls in Home pipe culverts including its painting	✓S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A/S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	N/A/S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/1km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

13/2
28/04/2020
(Signature)

NAME: S. K. Prasad.
E.E.