

FIELD INSPECTION REPORT

Date of Inspection: 28/12/20	District: East Champaran
Division: DHAKA	Length (km): 2.638
Name of the Road: Jolgaon To Baraula	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 34 08602037
Status of the Project: ☒ Ongoing/Completed/Under Maintenance	
Work is a case of: ☒ New Connectivity/Up gradation/ Maintenance	New M/R

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A
g)	Compaction of flank/slope & raincuts if any	Yes/No N.A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No N.A
4.	Compliance History	
a)	Status of ATR's & any others	N.A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

Bindu Rajar
(Signature) 28/12/20

NAME:

Bindu Rajar

DESIGNATION:

Executive Engineer
P.W.D.
Regional Laboratory Darbhanga