

FIELD INSPECTION REPORT

Date of Inspection : 28/11/2020		District: Nawada	
Division : Rajauli		Length (km): 2.458 km	
Name of the Road: Govindpur Road to Khairi road Tak			
Scheme/Programme: MAINTENANCE 3054		Road Id No.:	
Package No.:		Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	✓ S/U	
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No <i>re-cut.</i>	
2.	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SR/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA S/SR/U	
c)	Condition of railings/slab/approach for Bridges	NA S/SR/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	NO	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SR)	
Unsatisfactory (U)	

NAME:

Sri Kant Prasad
E.E.

MS
28/11/2020
(Signature)