

FIELD INSPECTION REPORT

Date of Inspection: 28/11/2020		District: Nanded	
Division: Rajale		Length (km): 4.00 km	
Name of the Road: Govindpur Road to Tataraga Tal.			
Scheme/Programme: MAINTENANCE NEW		Road Id No:	
Package No.:		Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	SR	
b)	Condition of Surfacing	SR	
c)	Riding Quality	SR	
d)	Road Camber	SR	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No/Not checked.	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	NA/SR/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA/SR/U	
c)	Condition of railings/slab approach for Bridges	NA/SR/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	NO	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SR)	
Unsatisfactory (U)	

13/2
28/11/2020
(Signature)

NAME: