

FIELD INSPECTION REPORT

Date of Inspection: 28/11/2020		District: Mandla	
Division: Rajauli		Length (km): 2.180 km	
Name of the Road: M.H.31 Simanah to Nandhan chhapala			
Scheme/Programmes: MAINTENANCE		Road Id No.:	
Package No.:		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New/Connecting/Up gradation/ Maintenance			
Sl. No.	Parameter to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓S	
b)	Condition of Surfacing	✓S	
c)	Riding Quality	✓S	
d)	Road Camber	✓S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA/Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	NA/Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓Yes/No/Remarks	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRU	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA/S/SRU	
c)	Condition of railings/slab approach for Bridges	NA/S/SRU	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board-5m & 200m stones/Pavement road markings are provided and maintained	✓Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	NO	

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRU)

Unsatisfactory (U)

(Signature)

NAME:

Sri Kant Prasad
E-E.