

FIELD INSPECTION REPORT

Date of Inspection : 28/11/2020		District: Nawada	
Division : Rajauli		Length (km): 7.930 km.	
Name of the Road: NH 31 Pachgawan more to Sakaspur Bk			
Scheme/Programme: MAINTENANCE 3054		Road Id No.:	
Package No.:		Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		✓ S/I
a)	Road Junction condition		✓ S/I
b)	Condition of Surfacing		✓ S/I
c)	Riding Quality		✓ S/I
d)	Road Camber		✓ S/I
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		N/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)		N/A Yes/No
g)	Compaction of flank/slope & raincuts if any		✓ Yes/No raincuts.
2.	Cross Drainage		✓ S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting		✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		N/A S/SRI/U
c)	Condition of railings/slab/approach for Bridges		N/A S/SRI/U
3.	Road Furniture		✓ Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		✓ Yes/No
4.	Compliance History		No
a)	Status of ATR's & any other		No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

28/11/2020
(Signature)

NAME: Sri Kant Prasad.
E.E.