

FIELD INSPECTION REPORT

Date of Inspection :	23/12/2020	District:	Saran / Chapra
Division :	Chapra-2	Length (km):	3.24
Name of the Road:	Madhopur to Makhpur (Benghara via Rudalpur)		
Scheme/Programme:	MAINTENANCE (3054/mr) old.		
Package No.:		Road Id No.:	31306300824
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	-S/U
b)	Condition of Surfacing	-S/U
c)	Riding Quality	-S/U
d)	Road Camber	-S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	- S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	- S/SRI/U
c)	Condition of railings/slab/approach for Bridges	- S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	'S, ✓
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

23/12/20
(Signature)

NAME: Chandravir Narayan
DESIGNATION: T.A. (Ex-Gr)