## FIELD INSPECTION REPORT

Jate of Ir	spection: 28/12	1000	District: Kartehan	
Name of	Road:	Radho	District: Kortham magan To Tetuliya M. Tola	
Scheme	neme/ Programme: MAINTENANCE			
Package	No.		Road ID No.	
Status of	the Project: Onging/Completed/Under Maintenance			A ST MAN TO THE THE
Nork is a	case of: New Connectivity/ Up Gradation/ Maintenance			
SI.No		Para	meters to be Checked	Remarks
1	Pavement			
a)	Road Junction Condition			S/U
<del></del>	Condition of Surfacing			S/U/
	Riding Quality			S/U/
	Road Camber			SAU
9)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No
	Contraction Joints provided or not (CC Pavement)			Yes/No
	Compaction of flank/slpoe & raincuts if any			Yes/No
	Cross Drainage			
	Condition of headwalls inn Humepipe culverts including its painting			S/SRI/U
	Condition of Abutment & Wings walls, Slab in RCC culverts			S/SRI/U
	Condition of railings/slabs//approach for Bridges			S/SRI/U
	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.			Yes/No
	Compliance History			
a) :	Status of ATR & any others			

Overall Grading:

Satisfactory (S)		
Satisfactory but req	SRC	
Unsatisfactory (U)		

Name: Ammendia North Thaleer Degisnation J.B (Signature)