


## FIELD INSPECTION REPORT

Date of Inspection: 28/12/2020		District: Kailash
Name of Road:		T03 To Haspura East Tola.
Scheme/ Programme:	MAINTENANCE	
Package No.	Road ID No.	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/ Up Gradation/ Maintenance	
Sl.No	Parameters to be Checked	Remarks
1	<b>Pavement</b>	
a)	Road Junction Condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2	<b>Cross Drainage</b>	
a)	Condition of headwalls in Humepipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wings walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slabs/approach for Bridges	✓ S/SRI/U
3	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/Pavement road markings are provided and maintained.	✓ Yes/No
4	<b>Compliance History</b>	
a)	Status of ATR & any others	

Overall Grading:

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name: Anvendra Nath Thakur  
Designation: J.B.

  
 (Signature)