FIELD INSPECTION REPORT

Date of Inspection: 26/11/020			District:	Kathan	1		
Name of	Road:	Katilan	Monitari	pwd Road Bandar To K	assipu	^	
Scheme/	Programme: MAINTENANCE						
Package	No.		Road ID No				
Status of	the Project: Onging/Completed/Under Maintenance						
Work is a	case of: New Connectivity/ Up Gradation/ Maintenance						
Sl.No	Parameters to be Checked					Remarks	
1	Pavement						
a)	Road Junction Condition					<i>S</i> /U	
b)	Condition of Surfacing					S/U	
c)	Riding Quality					S/U/	
d)	Road Camber					"S/Ú	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement					Yes/No	
f)	Contraction Joints provided or not (CC Pavement)					Yes/No	
g)	Compaction of flank/slpoe & raincuts if any					Yes/No	
2	Cross Drainage						
a)	Condition of headwalls inn Humepipe culverts including its painting					S/SRI/U	
	Condition of Abutment & Wings walls, Slab in RCC culverts					S/SRÍ/U	
c)	Condition of railings/slabs//approach for Bridges					S/SRI/U	
3	Road Furniture						
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained. Yes/No					Yes/No	
4	Compliance History						
a) :	Status of ATR & any	others					
	A 1 5 14 14 14 14 14 14 14 14 14 14 14 14 14		9 (5.7)	to the state of th			

Overall Grading:

Satisfactory (S)		
Satisfactory but requires Improvement(SRI)	SRC	
Unsatisfactory (U)		

Name:

Amrendra Ylath Thaken

Degisnation

(Signature)