

FIELD INSPECTION REPORT

Date of Inspection: - 28.12.20		District: - Kishanganj
Division: - Kishanganj-I		Length(km): - 2.843 K.M
Name of the Road: L052 - T07 TO Kekahatti		
Scheme/Programme: PMGSY		
Package No.: - BR-18R-69		Road Id No.: 2120580 2086
Status of the Project: Ongoing/Completed /Under Maintenance		
Work is a case of: ☒ New Connectivity/ ☐ Up gradation / ☐ Maintenance		
Sl. No	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints Provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank / shop & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	N/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	- NO

Overall Rating :

Satisfactory(S)	- S -
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory(U)	-

NAME: Er. Radheshyam prajapati
J.E, R.W.D, Bahadurganj-I

28/12/20
(Signature)
J.E