## FIELD INSPECTION REPORT

Date	of Inspection : 2	5-12-2020	District: Gropalgang	
Divisi	CW CWA: no	Gopaldary-2	Length (km): 2.014.	- T
Name	of the Road: S	idhwalia Baldin	pwo road to Darkilly to	of Hastlan
Scheme/Programme: MAINTENANCE		MM(1)(SC)	the same of the same of	
Package No.:		_	Road Id No.:	
_	of the Project:	Ongoing/Completed	/Under Maintenance	
Salar Salar Ch	s a case of:	and the second s	p gradation/ Maintenance	- Consider
SI. No.		Parameters to be checked		Remarks
1.	Pavement .			in the second
a)	Road Junction condition		S/U	
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2	Cross Drainage	Gui alla		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
3)	Condition of railings/slab/approach for Bridges			S/SRI/U
	Road Furniture			20 A
	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
	Compliance His	lory		
S	Status of ATR's & any others			37

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

—

Note-Danage due to blood.

(Signature)

NAME: Subhash chandra Verma

DESIGNATION: 3.E.